


## Hanover Countryside Elementary School

6 South Bartlett Rd, Streamwood, IL 60107

BUILDING SUMMARY			
Gross SF	46,386	Number of Levels	2
Year Built	1954	Number of Additions	3







LEVEL 1

ENROLLMENT METRICS


894 Occupancy\*\* **Effective Capacity** 488 **Total Enrollment** 393

**Occupancy:** the maximum number of people that can be housed in a space in accordance with the building/ fire code

\*\*NOTE: Occupancy is NOT the recommended number of students for a space, it is the maximum allowed by code.

**Effective Capacity:** the amount of students a school can effectively support based on the District's current practices and future vision for teaching and learning. This is calculated based on ISBE's square footage per student guideline. Calculated based on core classrooms, science labs and Special Education spaces.

**Enrollment:** number of students that attended the facility in 2019-2020.



\* This comparison notes the difference between Hanover Countryside Elementary School area per student in comparison to the current National average as noted in the 2015 School Construction Report. The master planning process will produce outcomes pertinent to the District as a whole. This is just one metric to compare space.

118 square feet • 150 per student square feet

Hanover Countryside School

2015 National Low **Ouartile Number** 



Furthest approximate travel time from one location to another for an average Kindergarten Student.



Furthest approximate travel time from one location to another for an average **Fourth Grade Student.** 

\* Guideline Acreage recommended by acres plus 1 acre per every 100 students \*\* School has IGA with Park District

> **1954** 1959

1960 **1991** 



Commons / Cafeteria Science Lab Core Classroom Elective Classroom Gym / Fitness Kindergarten /ECC Learning Center Media Lab

Performance Venue Performing Arts Classroom Resources

Special Education Stem / Hands-On Learning Restrooms

Student Support Visual Arts

OmO Travel Path Under-sized space

Room Capacity based on ISBE Guidelines



Phase 1 Snapshot January 27, 2021 DLR Group

Facility Condition(35%) FCI	<b>C</b> .23
Water Usage(5%)	Α
Gallons/SF Energy Usage(10%)	4.5 D
Ellergy Usage(10%)	U

SYSTEM

BUILDING

ВУ

>

Energy Usage(10%)			
70.4kBTU/SF/yr			
20.8kBTU/SF/yr			
49.6kBTU/SF/yr			

#### AGGREGATED FACILITY GRADE

6.6/10

7.2/10

7.6/10

5.8/10


5.7/10

118


50%

Yes/No


Educational Adequacy grades were determined by a survey issued to staff. Square Foot/Student grades were determined by building area and enrollment. Facility grades are determined building assessments. Water grades were determined by comparing utility data to the Commercial Buildings Energy Consumption Survey. Energy grades were deteremined by comparing utility data to the US Dept of Energy's Building Performance Database. Percent in parenthesis indicates weight of category in aggregate facility grade.



This chart indicates the approximate cost of deferred and anticipated maintenance (in dollars) of items assessed by building system. Highlighted items indicate those items in immediate need, code requirement, poor and fair condition.




Energy Use Intensity (EUI) is a key metric that expresses a building's energy use as a function of its size. Generally, a low EUI signifies good energy performance



Water usage is a key metric that expresses a school's water use and total cost of water in comparison to the other elementary schools in the district.

Observing representative classrooms within the school through a typical day allows the design team to quantify how learning spaces are used. Measurements are averaged from all classrooms visited.



# FACILITY BY CONDITION \$2.27M Good

COS

WATER

+

USAGE .

WATER

This chart indicates the approximate cost of deferred and anticipated maintenance (in dollars) based on condition of assessed items.

### What's a Listening Tour?

STENING TOUR

Staff surveys (Listening Tours) were sent to each school where faculty gave input about the strengths and weaknesses of the building. The following five comments highlight common themes and concerns.

#### **Listening Tour Comments From Staff**

- · Most of the classrooms are adequate in terms of space and condition. Teachers like that the classrooms have windows.
- There is a whole section of the building that doesn't have an adult bathroom. The only adult bathrooms are near the front door.
- •The entire expanse of asphalt including driveways, playgrounds and walkways needs to be redone because they are cracked and dangerous. There are large chunks of asphalt that come up where students are supposed to play foursquare.
- Teachers who responded indicated that the library needs the most improvement.

## COMPARED TO COHORT Fair \$3M Good \$2M ECTION. Poor \$1M Excellent \$0M OLLI $\bigcirc$ \$1201 4 FACILITY

This chart indicates the approximate cost of deferred and anticipated maintenance (in dollars) based on condition of assessed items in relation to the entire cohort of buildings.



#### How is this information collected?

The goal of the DLR Group integrated design team is to collect multiple **qualitative and quantitative data points** around the same set of items - for example energy use, air quality, or learning behavior - in order to **form a holistic picture**. The team collects these data points through the use of sensors (in the space for 1-7 days), spot measurement equipment, expert walkthroughs, focus groups, surveys, and ethnographic observation techniques. The results are validated by cross-checking data points, such as a survey answer and a spot measurement, that should relate to one another.